

PRODUCT SAFETY RECALL

Briggs & Stratton Announces Recall of BLACK DIAMOND LOG SPLITTER Powered by Briggs & Stratton® 250cc Engine

**Brand / Model Number:**

Black Diamond / Model Number
BDBS32T (32 ton)

Engine Serial Number Range:

1904085275251 - 1905085786452;
1906146333235 - 2004080670911;
1912319442579 - 2012073736714

Hazard: An incorrect engine ignition coil and flywheel may lead to hard starting and possibly engine kick back, a potential injury hazard to the operator.

Recalled Product: Black Diamond log splitter, Model Number BDBS32T (32 ton), sold from April 2019 through January 2021, powered by Briggs & Stratton 250cc engine, model number 15T232-0011-F8, with serial numbers between 1904085275251 - 1905085786452; 1906146333235 - 2004080670911; and 1912319442579 - 2012073736714

Remedy: Consumers should stop using the product immediately and contact their local authorized Briggs & Stratton dealer for engine repair. To find your local Briggs & Stratton dealer, visit www.briggsandstratton.com and under the Support dropdown, select Dealer Locator and filter for engine repair.

For More Information

Contact Briggs & Stratton toll-free, at 800.999.9444 (Monday through Friday 8:00 AM - 5:00 PM Central Time) for assistance or your local authorized Briggs & Stratton dealer.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission.

Post until September 1, 2021