

IMPORTANT SAFETY RECALL

STIHL TS 410 and STIHL TS 420

The flywheel can break apart while the engine is running, posing a projectile hazard to the user or bystanders.



Recall to repair certain TS 410 and TS 420 cut-off machines manufactured between January 2021 and April 2021, **serial number range 189442634 to 189969357.**Machines with serial numbers outside this range are not included in the recall.

Immediately discontinue use of a recalled TS 410 or TS 420 cut-off machine and take it to an authorized STIHL dealer for a free repair.

For further information, contact STIHL Incorporated:

1 (800) 233-4729

www.stihlusa.com

e-mail: stihlrecall@stihl.us